Defect list for Building Service Centre


4-room · Blk 000A #00-00 (sample)

Keys collected: 17 Aug 2026 · Report date: 16 Oct 2026 · 5 defects

No.	Room	Exact spot	Defect	Status
#01	Entrance	Main door, top hinge side	Door rubs frame	Fixed
#02	Living & dining	Floor near balcony door, 2 tiles	Hollow tile	Fixed
#03	Living & dining	Wall behind TV point	Paint patch	Fixed
#04	Kitchen	Floor trap by the sink	Water pools	Re-check
#05	Common bathroom	Shower wall, 3rd row from floor	Chipped tile	Reported

Floor plan


Rooms are labelled with the defects found there; numbered dots mark exact spots (green = fixed).



Photos

#01 Door rubs frame


Entrance · Main door, top hinge side



Sample photo · Door rubs frame

#02 Hollow tile


Living & dining · Floor near balcony door, 2 tiles



Sample photo · Hollow tile

#03 Paint patch


Living & dining · Wall behind TV point



Sample photo · Paint patch

#04 Water pools


Kitchen · Floor trap by the sink



Sample photo · Water pools

#05 Chipped tile

Common bathroom · Shower wall, 3rd row from floor



Sample photo · Chipped tile